

MAIN BUILDING GEN


Inspection Number	16171921	Customer Name	Health profession council south africa
Serial Number	2GG01316	Customer Phone	0822922186
Make	CATERPILLAR	Customer Email	VincentMo@hpsc.sa.co.za
Model	3406	Work Order	2100369995
Equipment Family	ENGINE - GENERATOR SET	Completed On	2024/02/20 16:06:48
Asset ID	Health profession council south africa	Inspector	Thabelo Mkhabele
SMU	272.8 Hours	PDF Generated On	2024/02/20

Work to be performed.

1. Doors to close properly



2. Install fuel shut of valve system.



3. Replace fuel system pipe system.



4. Fuel lines and piping - the supply and return piping needs to be replaced.



5. Change belts.



METRODEN BUILDING GEN

Inspection Number	16167245	Customer Name	Health profession council of South africa
Serial Number	PK51589*U044796Y	Customer Phone	0822922186
Make	PERKINS	Customer Email	VincentMo@hpcsa.co.za
Model	3464/1500	Work Order	2100369995
Equipment Family	ENGINE - GENERATOR SET	Completed On	2024/02/19 19:51:15
Asset ID	Health profession council of South africa	Inspector	Thabelo Mkhabele
SMU	237.7 Hours	PDF Generated On	2024/02/19

Work to be performed.

1. Replacement of battery part number 1111k



2. Install fuel shut-off valve.

